

AIR BARRIERS AND COMMISSIONING

Owner and Developer Perspective

Ed McNamara
Turtle Island Development LLC
Portland, Oregon

OVERVIEW

- Developer/Owner Perspective
 - Value of Air Barrier and Commissioning?
 - Costs of Tight Air Barriers
 - Challenges of Air Barrier Design and Installation
 - HVAC, Structural, Quality Control
 - Challenges of Measurement and Testing
 - Experience with Whole Building Pressurization

What I Develop: Midrise Wood-frame Apartments

SITKA APARTMENTS - 2005



RAMONA APARTMENTS - 2011



Value of Air Barriers and Commissioning

- I'm a big fan of both
 - Started Ramona design with 8 massing models, then studied 12 options for air/moisture/thermal barriers (opaque wall R-value, energy use), then modeled whole wall R-value with 3 different windows
 - Use an envelope consultant/building scientist
 - Extensive water/air testing – mock-up, in place
 - Energy modeling and track actual energy use
 - Blower door tests on apartments, whole building pressurization on Ramona

Barriers for Developers


- For many developers
 - No \$ payback from extra cost unless
 - Intending to hold long-term and
 - Building owner pays for heat and air conditioning
 - Costs could include
 - Costs of barrier design and installation
 - Related costs from changes in HVAC
 - Possible increases in operating costs
 - Risks of failures

COSTS OF TIGHT AIR BARRIERS

- Sitka - with tight air barrier
 - Added construction costs
 - Sealed joints
 - Sheet metal lining for supply and exhaust shafts (to reduce leakage)
 - Separate HVAC for laundry
 - 14% higher utility costs for make-up air (3,000 CFM vs. 2,625 CFM after reminding mechanical engineer after air-tightness)


ENVELOPE INFILTRATION – TYPICAL

Cheap for owner, expensive for tenants



ENVELOPE INFILTRATION – SITKA

Added heating/cooling for owner, lower for tenants



CHALLENGES – In the field

- Sitka used sealed joints on exterior gypsum
- Ramona used taped Tyvek
 - Sealed all horizontal joints, assumed vertical joints fell on studs and were relatively tight
 - Framers used pre-fabricated walls,
 - Came out in 12' lengths with sheathing installed
 - Saved costs and time, but
 - Left a large gap every 12' on wall

Sitka – Sealed joints on gypsum




RAMONA Vertical joints with gaps



CHALLENGES – from the design team

- Ramona cornice construction detail changed by design team
 - Had cornice built as part of roof truss instead of framing it onto wall
 - Improved structural attachment, but
 - Required venting cornice
 - Air barrier had to make transition from outside of sheathing to inside of framing
 - Became impossible to get tight seal

Ramona Cornice



Ramona Cornice



Ramona Cornice



CHALLENGES - Quality control

- Ramona air barrier design relied on Tyvek being airtight
 - Installers left loose ends flapping in wind, potentially tearing at staples
 - Masons had to cut Tyvek to install brick ledgers
 - Ledgers didn't arrive
 - Left massive slices in Tyvek in courtyard on windiest day of the year

Tyvek Installation



Tyvek Installation



CHALLENGES - Products

- Patio Doors
 - Selected the best we could, but had extensive and repeated failures in water and air testing, both on mock-up and in field testing
- Window wrap material
 - At contractor's suggestion, upgraded to higher quality wrapping material
 - Found out after all cladding was installed that we got a bad run and had potential delamination

MEASUREMENT CHALLENGES

- What are we measuring?
 - Air barrier tightness or whole building tightness
- Ramona original plan for HVAC was to "compartmentalize" each apartment
 - Horizontal ducting of intake and exhaust
 - No connection to hall, no shared shafts
- Concerns about air-tightness
 - Multiple penetrations
 - Backdraft potential

MEASUREMENT CHALLENGES

- Blower door test results
 - Sitka - 0.166 ACH (incl. one high outlier)
 - Ramona – 0.1406 ACH
- 15% better with taped Tyvek instead of sealed gypsum

Controlling for other variables

- Was improvement a result of taped Tyvek or a result of other Ramona differences?
 - Smaller and better windows
 - Improved window wrap/installation
 - Better patio doors (after multiple adjustments)
 - Double layer of sheetrock with staggered joints
 - Minimal # of electrical boxes on exterior walls
 - Putty pads and gaskets at electrical/CATV boxes

WHOLE BUILDING PRESSURIZATION Unexpected Benefits


- Thought it would only help for next building
- Pressurization and thermal imaging (building heated to 23° - or 74° - for 2 days)
 - Found and corrected cornice leaks (thermal imaging and smoke pencils)
 - Found casements that needed adjustment
 - Added vestibule at elevator in garage
 - Added weather-stripping to secondary exterior doors (e.g. door from hallway to loading dock)

WHOLE-BUILDING PRESSURIZATION Thermal Imaging

Friday, March 4th 4:20 PM 55 degrees F
South Wall of Courtyard

Air leakage is visible at the roof to wall connection (A). It is not unusual to see air leakage at such intersections, especially at inside and outside building corners, as air barrier construction is difficult where the building geometry is complex. The brick ledge (B), is also visible as a clear thermal bridge, conducting heat through the building frame to the exterior. It is typical for brick ledgers to conduct heat unless themally isolated from the building frame. Note the heat signature at the outside edge of the soffit (C). The roof-to-wall intersection is the likely source of this warm air leakage.





WHOLE BUILDING PRESSURIZATION Casement windows

Saturday, March 5th 3:23 PM 68 degrees F
North Wall of Courtyard, Sixth Floor
Positively Pressurized

Air leakage is visible at the lower right corner of the operable casement sash (A), while additional minor air leakage is also evident at the top left corner of the operable sash (B). Although this window system features three gaskets, it is evident that insufficient compression of the gasket is the cause of air leakage at the operable unit. The window manufacturer has indicated that simple adjustments can be effected to improve the gasket compression for better air tightness.

WHOLE BUILDING PRESSURIZATION Added vestibule at elevators in garage



CONCLUSIONS

- In my experience....
 - Air barrier is important component of energy reduction and resident comfort
 - Requires integration with HVAC
 - Requires constant vigilance throughout design, construction, submittals, etc.
 - Need clearer goals about testing, need to isolate other variables in design

THANK YOU