



**NRC-CNRC**

From **Discovery**  
to **Innovation...**

# ***Evaluating the effectiveness of window/wall interface details to manage rainwater***

Prepared by :

Michael Lacasse, NRC and Silvio Plescia, CMHC


For the  
**2006 British Columbia Building Envelope Council  
Symposium - May 25**



National Research  
Council Canada

Conseil national  
de recherches Canada





## *Past and recent studies*

- *Building envelope failures*
- *Window performance*
  - *NRC & others*
  - *RDH 2002*


## *Window-Wall Interface Project*

- *Approach*
- *Results*
- *Summary of key findings*


# Recent Surveys

## ***Recent CMHC Surveys of Building Envelope Performance***

- *1995 – Survey of Building Envelope Failures in the Coastal Climate of British Columbia*
- *1999 – Wall Moisture Problems in Alberta Dwellings*
- *2001 – Study of High-Rise Envelope Performance In The Coastal Climate of British Columbia*



# CMHC Surveys of Building Envelope Performance



## *Key findings -*

- *(at least) 25% of the moisture problems associated with water ingress into wall assemblies were directly attributed to penetration through the windows or the window-wall interface*





# Recent Surveys

## ***Minnesota problems –***

***"Stucco in Residential Construction",  
A position paper by City of  
Woodbury (MN) Building Inspection  
Division, Update, February 9, 2005***

- ***Homes built in Woodbury since 1990 were experiencing major durability problems***
  - ***To date, 276 of 670 stucco homes built in Woodbury in 1999 have failed (ca. 41%)***
- ***Primary causes - Window leaks, lack of kickout flashing, improper deck flashing...above the wood framing.***





## ***Surveys - Why Did Walls Fail?***

- ***Inappropriate balance between wetting and drying mechanisms***
  - ***Exposure - walls got wet***
  - ***Details - let water in***
  - ***Sensitivity of assemblies - inability to drain or dry***



# Windows and the Building Envelope

*“Rain penetration is a major problem with glazing and must be controlled....”*

*Glazing Design - Canadian Building Digest #55 (CBD55) published in July 1964*

*“Many inquiries concerning rain penetration of exterior wall are received by the B.C. Regional Station.... and are focused on window installation practices.”*

*Rain Leakage of Residential Windows in the Lower Mainland of British Columbia – Building Practice Note No. 42 (BPN42)*

Division of Building Research,  
National Research Council of Canada  
November 1984

*“....reports on window performance problems in Atlantic Canada.....”*


*Building Research Note No. 210 (BRN No. 210) - 1984*

# Recent studies focused on windows and window installation

- ***BRANZ (NZ) studies (2002) - WANZ WIS Parameter Investigation***
- ***CMHC sponsored study (2002) - Water Penetration Resistance of Windows***
- ***GTI studies (2006) - Window Installation Methods Test Results***



# 2002 Water Penetration Resistance of Windows



***STUDY OF MANUFACTURING,  
BUILDING & INTERFACE DESIGN,  
INSTALLATION AND  
MAINTENANCE FACTORS***

**WINDOW  
TERMINOLOGY**

**SUMMARY  
OF STUDY**

**WINDOW  
INSTALLATION  
GUIDE**

***STUDY OF CODES, STANDARDS,  
TESTING AND CERTIFICATION***



BC Housing



Homeowner  
Protection Office


**RDH**



CMHC SCHL


# Partial Conclusions and Recommendations

- *Most frequent leakage path → L5  
(L5 : Through window-wall interface to  
adjacent wall assembly)*
- **L4 and L5** are considered “high” risk for  
consequential damage  
(L4 : through window to adjacent wall  
assembly)
- *Minor variation exists between window  
types with respect to leakage paths*



# Partial Conclusions and Recommendations

- The CSA A440 B rating performance criteria does not address the current dominant leakage paths that are associated with installed windows

	Leakage Paths	Risk of Consequential Damage Rating	Applicability of A440 Testing to Leakage Path
	L1 - Through fixed unit to interior	Moderate	Good
	L2 - Around operable unit to interior	Moderate	Good
	L3 - Through window to wall interface to interior	Moderate	Never
	L4 - Through window assembly to adjacent wall assembly	High	Sometimes*
	L5 - Through window to wall assembly interface to adjacent wall assembly	High	Never
	L6 - Through window assembly to concealed compartments within window assembly	Minor	Good

Depends on where window frame is attached to test frame

# Partial Conclusions and Recommendations

- *Manufacturers have to focus on the design of the entire installed window. This includes ...the interface with the perimeter building walls.*
- *Windows need to be ...installed with redundant assemblies.*
- *The addition of sub sill drainage to interface design would improve water penetration performance of installed windows*
- *Designers need “...to increase their focus on interface detailing, considering continuity of all of the critical barriers..”*
- *Installers need to have greater understanding of the manufacturing and building design strategy.*
- *The creation of a mandated or generally accepted certification protocol, would have a positive impact on quality control issues.*

e.g. →


***CMHC-NRC (with industry partners) initiate WWI project to evaluate water management performance of various window installation details***

- Possibility to evaluate different interface details and their ability to manage rainwater entry – evaluate robustness of design***
- Development of a “standards” approach in a laboratory setting – precursor to a field certification protocol***
- Benchmark “performance” of proposed designs***



# NRC/IRC Test Program

- *Develop procedure to assess rainwater ingress*
- *Evaluate specific window-wall interface details to determine how effective they manage rainwater intrusion*



Elevation view of the test frame

# Test Specimen







# Test Specimen

**Water Spray**

**$\pm \Delta P$  Pressure Difference**



## ***Test conditions represent range of climate conditions in Canada***

- *Test Pressures -*
  - *Ranges between 0 and 700 Pa (75, 150, 200, 300, 500, 700 Pa)*
- *Spray rates –*
  - *0.8, 1.6 and 3.4 L/min.-m<sup>2</sup>*
- *Wall system air leakage variations*
  - *0.3 to 0.8 L/s-m<sup>2</sup> at 75 Pa*
- *Spray rate maintained for 15 min. intervals at each pressure level – for a given system leakage*

# Variations selected

<i><b>Specimen</b></i>	<i><b>Siding Installation</b></i>	<i><b>Window Frame</b></i>
<i><b>W1</b></i>	<i><b>With Clear Cavity Behind Siding</b></i>	<i><b>Non-finned (box)</b></i>
<i><b>W2</b></i>		<i><b>Flanged</b></i>
<i><b>W3</b></i> <i><b>W4</b></i>	<i><b>Without Clear Cavity Behind Siding</b></i>	<i><b>Flanged</b></i>




# Overview - Specimen Details



Specimen	W1	W2	W3	W4
<b>OBJECTIVES</b>  To determine the effect of:	An extra seal at jambs and head of R.O. window junction, for — <ul style="list-style-type: none"> <li>• Box frame fixed window, sloped subsill and rainscreen wall</li> </ul>	Changes in protection of R.O. members, back dam at subsill, for — <ul style="list-style-type: none"> <li>• Fixed flanged window installed in a concealed barrier wall</li> </ul>	Two subsill drainage methods of flat sill with back dam for — <ul style="list-style-type: none"> <li>• Combination flanged window installed in a rainscreen wall</li> </ul>	Sealing WRB to window flange, for — <ul style="list-style-type: none"> <li>• Combination window with brick mould installed in concealed barrier wall</li> </ul>

# Specimen Details- W1






- ***Clear cavity behind siding  
(19 mm wood furring strips used)***
- ***Non-finned (box) window frame***
- ***Variation - extra sealant and backer rod at  
the jambs and head***


# Specimen Details- W1

V-side


B-side



**Variation (V-side)**  
Caulking and backer rod between  
window frame and rough opening



**Selected Practice**





Water from sloped subsill is directed back out to backup wall and is collected in trough beneath sill

## Wall 1 - Water entry summary

V-side


B-side



- Water entry affected by water spray rate and tightness of assembly (air barrier system leakage)
  - Higher rates of water spray and higher system leakage resulted in greater rates of water entry to collection troughs
- Water entry through the windows occurred mainly at:
  - 500 and 700 Pa chamber pressure.
- Restricted water entry for either “B” or “V” interfaces for assemblies having :
  - “NO deficiencies”, and
  - Selected deficiencies, with exception of “Step 4” deficiency
- “Step 4” Deficiency -  
(90 mm of caulking and backer rod removed from horz. joint)
- Significant increases in water entry to reservoir on both sides
  - “V” side permitted about half the rate of water entry as compared to “B” side



## Location of Deficiencies




W1

# Water Management + Deficiency

## Reservoir Water Entry - 03 ABS

V	B
03	03


W1



# Water Management + Deficiency


## Reservoir Water Entry - 08 ABS

V-side B-side



V	B
08	08

W 1



# Overview - Specimen Details




Specimen	W1	W2	W3	W4
<b>OBJECTIVES</b>  To determine the effect of:	An extra seal at jambs and head of R.O. window junction, for — <ul style="list-style-type: none"> <li>• Box frame fixed window, sloped subsill and rainscreen wall</li> </ul>	Changes in protection of R.O. members, back dam at subsill, for — <ul style="list-style-type: none"> <li>• Fixed flanged window installed in a concealed barrier wall</li> </ul>	Two subsill drainage methods of flat sill with back dam for — <ul style="list-style-type: none"> <li>• Combination flanged window installed in a rainscreen wall</li> </ul>	Sealing WRB to window flange, for — <ul style="list-style-type: none"> <li>• Combination window with brick mould installed in concealed barrier wall</li> </ul>


# Specimen Details - W3

- *Clear cavity behind siding (furring strips)*
- *Combination window, solid PVC with integral flange – top slider, bottom fixed*
- *Variation: Two subsill drainage methods of a flat sill with back dam*

V-side



B-side



Shims provide gap





Window installed  
over furring strips




V-side


B-side




**Exploded View  
Variation Side**




**Exploded View  
Selected Practice Side**






## W3 – “V”

V-side B-side




### Variation Side:

- 3-mm spacers create gap between window flange and backup wall, allowing drainage from rough sill area



## W3 – “B”


V-side B-side



### Selected Practice:

- Furring strips create 19-mm gap between window mounting flange and backup wall
- Permits water to drain from subsill area
- Collected in “upper” trough

W3






- For both sides of wall, 19-mm space behind siding expected to prevent water from reaching backup wall
- Water runs down cladding and is collected in lower collection trough

# Water Management with Step 2

V-side

B-side

## Subsill Water Entry - 03 ABS






# Water Management with Step 2


V-side

B-side

## Reservoir Water Entry - 08 ABS



W3





## W3 - Water entry summary

- *Combination window permitted substantial amounts of water to enter at high pressures*
- *No deficiencies - both sides of wall performed similarly*
  - *B-side allowed small rates of water to enter “reservoir” collection trough at low chamber pressures,*
  - *At higher pressures, rates were reduced given that water was diverted through window*
- *With deficiency (Same as W1 - caulking removed from outside corner of window)*
  - *caused significant amounts of water to enter V-side reservoir*
- *For this deficiency*
  - *B-side had reduced water entry as compared to V-side - water only entering reservoir and subsill at highest cascade rate*


## W3

What happens  
when a deficiency  
is introduced in  
sealant and backer  
rod at sill?



Water runs down  
window face and  
pools on protruding  
rigid sill flashing

Given shallow slope  
of sill flashing,  
“pooled” water  
surmounts ~ 4-mm  
flashing up-leg





V-side

B-side

W3 – “B”

## Selected practice side “B”:

- Once water passes behind rigid sill flashing - runs down window mounting flange
- 19-mm gap created behind cladding proves difficult, but not impossible to bridge
- Portion of water attains backup wall and is collected by trough
- Remainder runs down interior of cladding and collected at base of wall







V-side

B-side

W3 – "V"

### Variation side:

- Water follows similar path on this side
- However, mounting flange provides a better path to backup wall
- Water easily bridges 3-mm gap
- Contributes to larger amount of collection on this side of wall.




# Overview - Specimen Details



Specimen	W1	W2	W3	W4
<b>OBJECTIVES</b>  To determine the effect of:	An extra seal at jambs and head of R.O. window junction, for — <ul style="list-style-type: none"> <li>• Box frame fixed window, sloped subsill and rainscreen wall</li> </ul>	Changes in protection of R.O. members, back dam at subsill, for — <ul style="list-style-type: none"> <li>• Fixed flanged window installed in a concealed barrier wall</li> </ul>	Two subsill drainage methods of flat sill with back dam for — <ul style="list-style-type: none"> <li>• Combination flanged window installed in a rainscreen wall</li> </ul>	Sealing WRB to window flange, for — <ul style="list-style-type: none"> <li>• Combination window with brick mould installed in concealed barrier wall</li> </ul>

# Specimen Details- W4

- ***No clear cavity behind siding (no furring strips)***
- ***No J-trim or Drip cap Head Flashing***
- ***Combination window, solid PVC with integral flange – top slider, bottom fixed***
- ***Sealing as compared to not sealing WRB to window flange***



# Self-adhered Membranes

- **Strip of self-adhered flashing membrane over joint between window flange and sheathing membrane (not at sill)**







# Self-adhered Membranes





# Test Observations

- ***Sealing joints between window and wall using such approaches - not 100% effective, given that:***
  - ***Water found its way to interior via reverse lapping***
  - ***Created funnels that channelled water to inside***
  - ***Some water was trapped inside assembly***




Why was water observed to pool at head of window on Selected Practice side?

W4 - "V"

On Variation side –

- WRB is properly lapped over window flange, directing water to outside of wall




## W4 – “B”

- Review of Selected Practice side showed delamination of flashing membrane from WRB
- Creation of openings for water entry - “fish mouths”




Reverse lapping and “fish mouths”  
along length of SAF membrane  
permitted channelling of water up and  
over window flange and into cavity of  
wall/window interface



Additional 50 mm  
strip of adhered  
flashing  
membrane on B-  
side of wall



- Wall rebuilt with 150 mm of additional Head Flashing behind WRB
- Test results indicated that this alteration prevented water from entering wall cavity



# Observations - Wall Response

## Air Pressure Difference


- ***Effect on water accumulation on rough sill as related to:***
  - ***Location of highest air pressure drop in relation to location of plane of wetness***
  - ***Air leakage rate***

# Observations - Wall Response

## Effects of Pressure Distribution

### Specimen A:

High pressure drop ( $\Delta P$ ) across wetted airtight external plane




# Observations - Wall Response

## Effects of Pressure Distribution

### Specimen B:


Lower pressure drop across wetted “vented” external plane



Jamb detail  
(horz. sectional view)

# Observations - Wall Response Effect of Location of Plane of Airtightness

Reservoir Water Entry - 08 ABS



Same rate of wall air leakage, 2 different designs



# Results - Practical considerations

- ***Design decisions in regard to choice of:***
  - ***Method of installation in relation to climate loads***
  - ***Components***
    - ***Windows & window openings***
    - ***Self-adhered flashing membrane and tape***
    - ***Jointing products***
  - ***Redundancy in design***
    - ***Boxed windows – two seals or one?***
    - ***Cladding and sills***
- ***Care and sequence of installation***

# Installation related to climate loads

- *Water penetration at interface (in some instances) dependent on climate elements – i.e. water deposition, air pressure difference*
- *Generally (and as expected!)*
  - *Increasing water load on cladding increased likelihood of water entry – hence:*
    - *Reducing loads on cladding and window proper likewise reduces chance for water entry*
  - *Increasing pressure across interface also increases likelihood of water entry*
    - *Location of plane of air tightness in relation to presence of water - important*

# Lesson #1: The Rough Opening Will Get Wet: Drain it Out

- ***Flash and drain the rough opening***
  - *Protect moisture-sensitive materials from water absorption*
  - *Provide drainage path to outside, i.e. include*
    - *Sloped rough sill*
    - *Back dam*
    - *Water impermeable rough sill; up 150 mm on jambs*
    - *Provide ease of drainage from rough sill - out of wall assembly*
    - *Integrate with other elements that contribute to control of rainwater ingress (i.e. shingle lapping, sequencing)*

## ROUGH SILL FLASHING SYSTEM

## Lesson #2: Keep Air Barrier Tight and Dry

- *Current practice aims at sealing joints that can get wet: the joint between window frame (flange) and sheathing membrane*
- *Imperfect seals at which both water and higher pressure differences coexist drive water through seal imperfections*
- *Plane of higher pressure drop (Air Barrier System) should be in dry location, towards interior of joint*

# Future work

- **Report on Phase 1 expected in June 2006**
  - **A select set of windows and installation details investigated amongst many different possible combinations**
- **On-going testing with industry partners – Phase 2 BDTI and DuPont**
  - **Report on Phase 2 expected in fall of 2006**
- **Preparations for final Phase of project with PWGSC**
  - **Specimen preparation and testing – 2006; Results – 2007**
- **Additional interest by others in industry - Issues of interest:**
  - **Use of spray in-place foam for control of air leakage – how does use of foam affect rainwater intrusion and drainage?**
  - **Use of pan flashing – Is this approach a panacea for leaky windows?**
    - **What are the key installation details to ensure watertightness?**
    - **Does pan flashing affect thermal performance or risk to condensation at the window frame?**



# Acknowledgements

## ***Industry partners***

- ***CMHC***
- ***PWGSC***
- ***DuPont Tyvek Weatherization Systems***
- ***Building Diagnostic Technologies***

## ***Project consultants***

- ***Mr. David Ricketts, RDH Group, BC***
- ***Mr. John Vlooswyk, Building Envelope Engineering, AB***
- ***Mr. John Buchan, BLP, ON***
- ***Mr. Armand Patenaude, Patenaude-Trempe, QC***

## ***IRC/NRC/CMHC research team***

- ***Mr. Silvio Plescia***
- ***Ms. M. Rousseau***
- ***Mr. S. M. Cornick***
- ***Mr. M. Nicholls***
- ***Ms. M. Manning***
- ***Mr. G. Ganapathy***
- ***Mr. A. Jacob***
- ***Mr. S. Nunes***
- ***Mr. M. A. Lacasse***





**NRC-CNRC**

From **Discovery**  
to **Innovation...**

# ***Performance of Window-Wall Interface to Manage Rainwater***

Prepared by :

Michael Lacasse, NRC and Silvio Plescia, CMHC

For  
**2006 British Columbia Building Envelope Council  
Symposium**



National Research  
Council Canada

Conseil national  
de recherches Canada



**NRC-CNRC**

*Institute for  
Research in  
Construction*