

Studio Bell, Home of the National Music Centre A Building Envelope Case Study



→ Terminology

- Studio Bell = The building
- The National Music Centre (NMC) = The building owner and occupant
- NMC used to be The Cantos Music Foundation (Cantos)





- → NMC conducted an international design competition, in July 2009 five architects were short-listed
- → In September 2009 Allied Works Architecture were selected as the designers of Studio Bell





→ Project Team

- Owner and building occupant NMC
- Architect Allied Works Architecture
- Local Architect Kasian
- Project Manager DukeEvans Inc.
- Structural Engineer RJC
- Mechanical Engineer SMP
- Electrical Engineer Stantec
- Constructor CANA
- Owner's Building Envelope Consultant WSP
- Contractor's Building Envelope Consultant Morrison Hershfield



→ Project Timeline


- Design Competition 2009
- Detailed Design 2009 to 2014
- Construction 2013 to 2016

→ Cost and Funding

- Final Project Cost: \$191M
- Just over \$130M of funding secured to date from:
 - All levels of government
 - Private donations
 - Corporate donations and partnerships




Building Overview





→ Horizontally and vertically extruded terra cotta tiles



→ Horizontally and vertically extruded terra cotta tiles






→ Solid Walls – Horizontally extruded terra cotta tiles







→ Solid Walls – Horizontally extruded terra cotta tiles




































→ Glazing – Triple glazed curtain wall and skylights






→ Skylights







- → Winter Exterior Design Temperature:
 - -40°C (With special operating protocol)
 - -30°C with no special procedures required
- → Winter Interior Design Parameters:
 - 21°C +/-2°C
 - 40%RH +/- 5%













→ Access to curtain wall behind screens for cleaning + glass replacement










→ Calgary weather

- Freeze thaw cycles
- Ice formation






CKUP #1_17JAN2014








Construction Challenges





Material Compatibility and Manufacturers


































T3 - Sheathing Behind Cladding Clip System



43%

8.0
















Skylights





Skylights





Skylights

